

724 R92  
C-N-N 1/4  
935  
1994  
1988

- (71) SET standard Forest Service monument in rock mound from which bears a:  
 11" White Fir S 70° 34' E 17.8  
 10" White Fir S 31° 05' W 6.2  
 1/2" rebar with aluminum cap LS 2843  
 S 77° 51' E 0.51

724 R92  
C-N-N 1/4  
935  
1994  
1988

- (72) SET standard Forest Service monument in rock mound from which bears a:  
 11" White Fir S 11° 56' E 36.9  
 8" Cedar S 62° W 18.6  
 1/2" Rebar with aluminum cap LS 2843  
 S 69° 42' 55" E 5.44

- (73) FOUND 3/4" iron pipe with brass cap "GIL 36464"  
 (4.58 E of line)

- (74) FOUND standard BLM monument (1967) set in rock mound as per (R<sub>4</sub>) from which bears a:

16" Fir S 89° 25' E 15.3  
 36" Cedar S 76° 25' W 12.9

(11" Fir East 15.5 )  
 (30" Cedar S 76° W 13.2 ) (G)  
 (15" Black Oak S 67° E 21.8)  
 [not tied in]

- (75) FOUND standard BLM monument (1967) set in rock mound as per (R<sub>4</sub>) from which bears a:

8" Cedar S 86° 59' E 14.7  
 8" Cedar S 83° 11' W 11.5

( 6" Cedar S 84° W 11.9 )  
 ( 7" Cedar S 86° E 14.8 ) (G)  
 (29" Fir S 31° W 58.7 )

- (76) FOUND standard BLM monument set in rock mound (1967) as per (R<sub>4</sub>) from which bears a:

14" Cedar S 49° 12' W 19.3  
 17" Cedar N 41° 18' W 9.6

(17" Cedar N 41° W 9.2 )  
 (12" Cedar S 50° W 19.1 ) (G)  
 (26" Fir N 35° E 4.6 )  
 [Not tied in]

724 R92  
1/4 C. 1/4  
937 + 936  
1994  
1988

- (77) FOUND open 3/4" iron pipe on steep west slope as per (R<sub>6</sub>) and 1-R/S-35  
 Government topo calls insufficient to establish corner location in different position. Ecker indicated on R/S map 1-R/S-35 that he found 1 original bearing tree. No evidence of this tree at present time. Because of this statement and existing use, accepted 3/4" iron pipe as best evidence of original corner position.

REPLACED corner with standard Forest Service monument in rock mound from which bears a:

15" Douglas Fir with old healed blaze  
 N 15° 22' W 12.5  
 11" Douglas Fir N 71° 03' E 24.2

RECORD OF SURVEY  
 FOR  
 U.S.D.A. - PLUMAS NATIONAL FOREST  
 'BUTTERFLY CADASTRAL SURVEY'

Being portions of Sections 17, 20, 27, 28, 29 and 33

T. 25 N. - R. 9 E. - M.D.M.

PLUMAS CO., CA

JUNE, 1988

LIPPINCOTT SURVEYING

1007 BILLE ROAD - P.O. BOX 671 - PARADISE, CA 95967  
 Ph. 916 / 877-4300

SHEET 5 OF 5 SHEETS