

DETAIL NOT TO SCALE

FD. A STD. U.S.F.S. MON.
SET FOR THE EAST 1/4
OF SEC.15, T24N R8E MDM.
(SEE 6 RS 83) (LS 5147)
ESTABLISHED WITH
ORIG. G.L.O. EVIDENCE

S114'00" W(R4)
34.20' (R4)

N40°17'49"E 644.95'

NO CORNER FOUND
PER (R4)

S114'20"

N40°17'49"E 644.95'
S38°53'W 505.80' (R4)

NOTE:

I FOUND NO CORNERS ALONG
THE SOUTHEASTERLY BOUNDARY
OF 6 PM 37, THE CORNERS WERE EITHER
LOST OR OBLITERATED. HENDERSON'S
MAP SHOWED THAT HE SET 1/2 STEEL
PINS WITH PLASTIC CAPS. FELL
IN DRIVEWAY.

6 PM 37
PARCEL 1

THIS CORNER FELL IN THE
MIDDLE OF A GRAVELED DRIVE
WAY AND HAS BEEN OBLITERATED
ACCORDING TO AN ADJACENT
LAND OWNER.

NO CORNER FOUND
PER (R4 & R5)

58

200.00' (R2&M)

2