

CORNER RECORD

City of Unincorporated Area


Agency Index

448-449

Document Number

County of Plumas, California

Brief Legal Description Lot 5, 6 Maps 128, S 1/2 of Section 18, Township 24 North, Range 10 East, M.D.M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units _____ Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

Date of Survey June 13, 2022

PLS Act Ref: 8765(d) 8771 8773 Other:

Corner/ Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):

Found 1/2" Rebar with Caps as noted per 6 M 128 & 12 PM 109 as shown on sketch.

Reset missing NE corner & westerly cul-de-sac corner of Lot 5 from found monuments as shown.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on June 16, 2022

Signed John A. Alfred P.L.S. or R.C.E. No. LS 8463



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received July 20, 2022

and examined and filed 8/20/22


Signed R. Tom Shultz P.L.S. or R.C.E. No. 30515

Title County Surveyor



County Surveyor's Comment _____

Bearings and Distances shown hereon are Record
and Measured per 6 M 128 unless noted.



LEGEND

- FOUND 1/2" Rebar with Plastic Cap RCE 22836 per 6 M 128
- FOUND 1/2" Rebar with Aluminum Cap LS 6051 per 12 PM 109
- ∅ SET 1/2" Rebar with Plastic Cap LS 8463