


CORNER RECORD

COUNTY OF PLUMAS T. 28N R. 7E M.D. MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT October 16 1991



N 1/4 corner Section 13

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


Found stone md. in old burn area underneath Manzanita bush. Matches GLO call to Bailey Creek 3 chains east. Fd old Fir stump hole $543\frac{1}{2}^{\circ}W$ 27.7'

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Rebuilt stone mound; tied to section corner $1/2$ mile east; set $1\frac{1}{2}$ " iron rod capped "L.S. 3989"

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ STATION _____
 EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON October 16 1991

SIGNED: Fred R. Bagel

L.S. or R.C.E. No.: L.S. 3989

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 12/18 OF 1991 AND EXAMINED AND FILED 12/27 1991

BY: R. Tom Shanta

TITLE: East. Co. Engineer

DOCUMENT No. 62

STATEMENT ON BACK OF SHEET

YES NO