

CORNER RECORD


Document Number

230

SE1/4 Section 24, T.22 N., R.12 E., M.D.M.

County of PLUMAS, California

Brief Legal Description LOT 8 OF MOUNTAIN VIEW ESTATES RECORDED IN BOOK 8 OF MAPS AT PAGE 6



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey MARCH 28, 2003

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown and described on attached sketch and as shown on 8 M 6.

A description of the physical condition of the monument as found and as set or reset:


Found points as described and in good condition. Points set as shown on attached sketch.

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 1, 2003.

Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4-16 2003 and
examined and filed 4-28 2003.Signed R. Tom Stank Title Plumas County Surveyor

County Surveyor's Comment _____



NOTE: ALL BEARINGS AND DISTANCES
ARE RECORD PER 8 M 6.

$$1'' = 200'$$

LEGEND

- FOUND 1/2" rebar and Plastic Cap RCE 22836
- SET 5/8" Rebar & Plastic Cap LS 2843
- Nothing found or set

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571