

ENGINEERING DEPARTMENT

520 MAIN STREET, RM 120 QUINCY, CA 95971 (530) 283-6222, FAX (530) 283-6135



To: Mr. James Eddy Jr.
From: Mike Kroencke, Engineering Technician
Re: Corner Record for Lot 11, Block 6, Mount Lassen View Addition

Dear Sir,

This office is ready and willing to submit this corner record "as is" to the County Surveyor, although the following items would be desirable for the record.

Instead of "found monument per 4 PM 116" would you please provide a description of the physical condition of the monuments found. ✓

Would you please indicate "no record" for those monuments found. Specifically 1 1/2 inch IP no tag, and also, 1/2 inch rebar and plug LS 4647. ✓

- * Did you happen to locate any monument(s) referred to on 3 PM 94 located on the North side of Third Street along the South side of lots 7 and 8 of Block 5? *no*
Also did you happen to locate any monument(s) referred to on 4 PM 7 located on the South side of Lot 24, Block 3, along the North side of Third Street and West of Second Avenue? The location of these monuments would help establish the right of way which defines the blocks. *no*

Thanks

Mike

* Due to the fact that the distances measured between the found monuments in Block 6 matched record, monuments in other blocks were not looked for.

PS: Sorry for returning this back after so long. It got misplaced & I just found it.

Jim Eddy



ENGINEERING DEPARTMENT

520 MAIN STREET, 100 120 COUNCIL, CA 90012 (213) 259-6222, FAX (213) 259-6135

To: Mr. James Bddy Jr.
From: Mike Kroenke, Engineering Technician
Re: Corner Record for Lot 1, Block 6, Mount Lassen View Addition

Dear Sir,
This office is ready and willing to submit this corner record "as is" to the County Surveyor, although the following items would be desirable in the record:

Instead of "found monument per 4 PM 10", would you please provide a description of the physical condition of the monument found.

Would you please indicate "no record" for those monuments found specifically 1/2 inch 10 iron rod and 1/2 inch 10 iron rod and 1/2 inch 10 iron rod.

Did you happen to locate any monument(s) referred to on 4 PM 94 located on the North side of Third Street along the South side of lots 7 and 8 of Block 2? Also did you happen to locate any monument(s) referred to on 4 PM 7 located on the South side of Lot 2, Block 2, along the North side of Third Street and West of Second Avenue? The location of these monuments would be to establish the width of way which defines the blocks.

Thank you

Mike

* Due to the fact that the distances measured between the found monuments in Block 6, no master record monuments in other blocks were not looked for.

Jim Bddy

P.S. Sorry for returning this back after so long. It got misplaced & I just found it.