

CORNER NOTES

- ① Cor #1 Corner Monument Set On easterly sideline of Calif Hwy 89 Right-of-Way, As Per Dept. Of Public Works Record Maps 9-83-125.01 and 9-83-125.02, From Which An 8"x8" Cedar Post Bears East 0.3 Feet At Intersection Of Barbwire Fences.
- ② Cor #2 Corner Monument Set 0.3 Feet North Of 8"x8" Cedar Post At Angle Point In Barb Wire Fence
- ③ Cor #3 Corner Monument Set At Angle Point In Barb Wire Fence
- ④ Cor #4 Corner Monument Set 1.5 Feet North Of 32" Pine, Notched At Root Crown, Which Is Angle Point In Barb Wire Fence
- ⑤ Cor #5 From Corner Monument, A Standpipe For A Water Line, Apparently Passing Under The Middle Fork Of The Feather River To The Gravel Yard On Opposite Bank, bears S 83° 52½' E 124.7 Feet
- ⑥ Cor #6 Corner Monument Set 4.0 Feet East Of Gate In Barb Wire Fence
- ⑦ Cor #7 Corner Monument Set 1.0 Feet East Of Old Wood Fence Post, No Fence Attached
- ⑧ Cor #8 From Corner Monument, A 12" Pine, Notched At Root Crown, Bears S 19° E 5.0 Feet
- ⑨ Cor #9 From Corner Monument, A 23" Pine, Notched At Root Crown, Bears N 74° W 5.3 Feet
- ⑩ Cor #10 Corner Monument Set Approximately 8 Feet West Of Paved Road And 3" Below Surface Of Turnout, From Which A 17½" Pine Bears S 24½° W 23.7 Feet Notched At Root Crown.
- ⑪ Cor #11 Corner Monument Set On East Cutbank Of Dirt Road Approximately 13.5 Feet From Centerline
- ⑫ Cor #14 Corner Monument Set On Flat Shelf Below Large Railroad Fill
- ⑬ Cor #15 Corner Monument Set 1.5 Feet West Of Iron Gate On Dirt Road Along East Bank Of The Middle Fork Of The Feather River

NOTE: Centerline Of Middle Fork Of The Feather River Was Determined Photogrammetrically

NOTE: The Northeast And Southeast Corners Of The County Transfer Site Were Determined By Rotating The Measurements Recorded On 5 PM 63 To The Basis Of Bearing Shown For This Map.

- ⑭ Cor #19 Corner Position Is In Centerline Of The Middle Fork Of The Feather River And Is The Southeast Corner Of The County Disposal Site, as per 5 PM 63
- ⑮ Cor #20 Corner Position Is The Northeast Corner Of The County Disposal Site; Other Information Same As Note 14
- ⑯ Cor #21 Found ½" Iron Pipe W/ Tag & Nail For Northwest Corner Of The County Transfer Site, as per 5 PM 63, R.C.E. 13528
- ⑰ Corner Tie Found ½" Iron Pipe, No Markings. The Distance Between This Corner And That Noted In Note 16 Matches Exactly That Shown On 5 PM 63
- ⑱ Cor #22 From Corner Monument, A 21" Pine, Notched At Root Crown, Bears S 37° E 3.0 Feet
- ⑲ Cor #23 Corner Monument Set 1.5 Feet East Of 8"x8" Wooden Post At Corner Of Barb Wire Fence
- ⑳ Hwy. Monuments Found 6"x6" concrete monuments for California Highway 89 Right-of-way, as per Book 4 of Maps, Page 68, in the Plumas County Recorder's Office BEING 75' LEFT OF STA. "A" 384+85.15 B.C. AND 50' LEFT OF STA. "A" 350+57.44
- ㉑ ¼ - 10/15 Found 1½" Iron Pipe W/ 2¼" Cap, As Per 2 RS 119, Extending 2½" Above Ground In 8"x24" Stone Mound, From Which Bears A 24" Cottonwood N 51° W 45.8 Feet W/ Placerville Lumber Co. K-tag. No Bearing Trees Described In Original G.L.O. Fieldnotes. Corner Lies On Flood Plain Of The Middle Fork Of The Feather River. STAMPED R.C.E. 32780
- ㉒ 10/11 - 15/14 Found ½" Rebar W/ Plastic Cap Marked "R.C.E. 15265", Extending 3" Above Ground In 6"x24" Stone Mound, From Which Bears A 20" Pine N 62° W 23.4 Feet W/ Healed Blaze; A 22" Pine S 20° W 40.4 Feet W/ Healed Blaze. Corner Position Remonumented By California Division Of Highways During Realignment Of Hwy 70. No Evidence Found Of Original G.L.O. Bearing Trees.

NOTE: The Measurements Shown On This Map To The Western Pacific Railroad Are To The Centerline Of The West Track