

<p>T21N R8E CORNER No. 2 $\frac{1}{4}$ S11 $\frac{1}{4}$ S14 LS 4753 2002 FD. A T-BAR WITH TAG MARKED FOR CORNER AND LS 3079 IN A MOUND OF STONE (NO RECORD). SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID T-BAR ALONGSIDE. CORNER FALLS ON A STEEP SOUTH SLOPE IN TIMBER, 100'± NORTH OF OLD MOOREVILLE ROAD. FD. A 16" WHITE FIR, N34°E, 8.5' -HB LOCAL - NO RECORD FD. A 17" WHITE FIR, S9°E, 20.6' -HB LOCAL - NO RECORD NOTE: FD. SCRIBED SUGAR PINE FACE MARKED "1/4 S" ALONGSIDE MOUND.</p>	<p>$\frac{1}{16}$ C-C S14 CORNER No. 7 LS 4753 2002 SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A FLAT LAVA REEF, 60' SOUTHEAST OF MOOREVILLE RIDGE ROAD. SCRIBED A 20" PONDEROSA PINE, S36°W, 26.6' "CW 1/16 S14 BT" SCRIBED A 14" PONDEROSA PINE, S50 1/2°E, 65.4' "CW 1/16 S14 BT"</p>	<p>CORNER NOTES HB = HEALED BLAZE VS = VISIBLE SCRIBING (1) = REC. PER 2 R/S 81 (2) = REC. PER 7 R/S 140 (3) = REC. PER 5 RS 37 (4) = REC. PER 9 R/S 40</p> <p>T21N R8E CORNER No. 12 S15 S14 S22 S23 LS 4753 2002 FD. A T-BAR MARKED FOR CORNER AND LS 3079 IN A MOUND OF STONE (NO RECORD). SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID T-BAR ALONGSIDE. CORNER FALLS ON A MODERATE EAST SLOPE AT THE EDGE OF A MANZANITA PATCH.</p>	<p>$\frac{1}{16}$ S22 S23 LS 4753 2002 CORNER No. 17 FD. A 1" IRON PIPE IN A MOUND OF STONE. REPLACED WITH A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD AND REBUILT MOUND. CORNER FALLS ON A GENTLE SOUTHWEST SLOPE, 50'± NORTHEAST OF A LOGGING ROAD. SCRIBED A 5" WHITE FIR, S65°W, 6.6' "X BT" SCRIBED AN 11" WHITE FIR, N37 1/2°E, 10.7' "N 1/16 S23 BT"</p>	<p>T21N R8E CORNER No. 22 S2 S28 LS 4753 2002 FD. A 1/2" PIPE WITH A 2' ALUM. CAP IN A MOUND OF STONE MARKED FOR CORNER AND LS 2670. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID PIPE ALONGSIDE. CORNER FALLS ON A MODERATE EAST SLOPE IN TIMBER. FD. AN 18" PINE SNAG, S14°E, 22.4' VS REC. A 24" INCENSE CEDAR SNAG, S15°E, 23.1' (1) FD. A 17" WHITE FIR, S4°E, 16.3' -HB REC. AN 8" WHITE FIR, S4°E, 16.3' (1) FD. A 19" INCENSE CEDAR, N33°E, 30.8' -HB REC. A 12" INCENSE CEDAR, N33°E, 30.8' (1)</p>
<p>$\frac{1}{16}$ S11 S14 CORNER No. 3 LS 4753 2002 SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS AT THE TOE OF FILL OF ROAD 20N47. SCRIBED A 7" INCENSE CEDAR, S84°E, 18.9' "E 1/16 S14 BT" SCRIBED A 6" WHITE FIR, S30°E, 7.9' "X BT" FD. A 1" IRON PIPE - NO I.D., S11 1/2°W, 0.6' NO RECORD</p>	<p>T21N R8E CORNER No. 8 $\frac{1}{4}$ S14 S14 LS 4753 2002 SET A U.S.F.S. ROCK CAP IN A MOUND OF STONE. CORNER FALLS ON A FLAT LAVA REEF. SCRIBED A 20" JEFFREY PINE, N31°E, 52.0' "C 1/4 S14 BT" SCRIBED A 22" PONDEROSA PINE, S39°W, 64.2' "C 1/4 S14 BT"</p>	<p>FD. A 27" INCENSE CEDAR, S87°W, 9.9' -VS REC. A 30" INCENSE CEDAR, S87°W, 11.2' (1) FD. A 45" PINE SNAG, N39°E, 48.2' -VS REC. A 56" PONDEROSA PINE, N20°E, 48.2' (1) SCRIBED A 6" WHITE FIR, N70°W, 28.9' "X BT" SCRIBED A 6" WHITE FIR, S39°E, 46.7' "T21N R8E S23 BT"</p>	<p>T21N R8E CORNER No. 18 $\frac{1}{4}$ S21 S22 LS 4753 2002 FD. A 3/4" IRON PIPE WITH A 2" ALUM. CAP, "LS 2670 1959" IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID PIPE ALONGSIDE. SCRIBED A 5" WHITE FIR, S81°W, 8.6' "1/4 S21 BT" SCRIBED A 17" WHITE FIR, S43°E, 15.0' "1/4 S22 BT"</p>	<p>CORNER No. 23 T21N R8E CORNER No. 23 S21 S22 S28 S27 LS 4753 2002 FD. A 6 X 3 X 3 INCH (REC. 12 X 10 X 10 INCH) STONE, 3 NOTCHES SOUTH, 2 NOTCHES EAST IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND TURNED STONE FACE DOWN IN MOUND. CORNER FALLS ON A STEEP, SOUTHERLY LAVA FLOW, 20'± NORTH OF A SEASONAL CREEK. FD. A 23" INCENSE CEDAR, N87°W, 30.4' -VS REC. AN 8" CEDAR, N87°W, 46 LKS (GLO 1884) FD. A 12" INCENSE CEDAR, S36°E, 7.3' -VS REC. A 10" CEDAR, S6°E, 11 LKS (GLO 1884) FD. A 17" BLACK OAK, N80°E, 38.3' -HB REC. A 14" BLACK OAK, N80°W, 58 LKS (GLO 1884) SCRIBED A 13" INCENSE CEDAR, N52°W, 32.7' "T21N R8E S21 BT"</p>
<p>T21N R8E CORNER No. 4 S11 S12 S14 S13 LS 4753 2002 FD. A T-BAR TAGGED LS 3079 IN A QUARTZ ROCK MOUND (NO RECORD). SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID T-BAR ALONGSIDE. CORNER FALLS ON A MODERATE WEST SLOPE IN MID SIZE TIMBER AND LIGHT BRUSH. FD. A 14" WHITE FIR, S55°W, 18.7' -HB NO RECORD FD. AN 8" INCENSE CEDAR, N43°E, 22.8' -HB NO RECORD FD. A 23" WHITE FIR, S75°E, 30.2' -HB NO RECORD FD. AN 11" WHITE FIR, N31°E, 3.2' -HB NO RECORD FD. A 56" SUGAR PINE, S29°W, 18.7' -OPEN SCAR - NO VS REC. A 36" SUGAR PINE, S29°W, 29 LKS (GLO 1884)</p>	<p>T21N R8E CORNER No. 9 $\frac{1}{4}$ S14 S13 LS 4753 2002 NO EVIDENCE FD. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE IN TIMBER ON THE EAST SIDE OF A NORTH-SOUTH SKID ROAD. SCRIBED AN 11" DOUGLAS FIR, N24 1/2°E, 19.0' "1/4 S13 BT" SCRIBED A 6" INCENSE CEDAR, S54 1/2°W, 27.7' "1/4 S14 BT"</p>	<p>SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN TIMBER, 150'± NORTHEAST OF A LOGGING ROAD. SCRIBED A 14" WHITE FIR, N3°E, 9.0' "W 1/16 S14 BT" SCRIBED A 14" WHITE FIR, S26°E, 17.1' "W 1/16 S23 BT"</p>	<p>T21N R8E CORNER No. 19 $\frac{1}{4}$ S21 S22 LS 4753 2002 SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE EAST SLOPE, 10'± SOUTH OF A ROAD AT THE EDGE OF A CLEAR CUT. SCRIBED A 13" INCENSE CEDAR, S87°E, 110.7' "C 1/4 S22 BT" SCRIBED A 6" WHITE FIR, N18°W, 56.9' "C 1/4 S22 BT"</p>	<p>T21N R8E CORNER No. 24 $\frac{1}{4}$ S22 LS 4753 2002 NO EVIDENCE FD. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHEAST SLOPE IN TIMBER AND SPARSE BRUSH 35'± FROM SKID ROAD. SCRIBED AN 8" INCENSE CEDAR, S28°E, 5.6' "1/4 S27 BT" SCRIBED A 9" SUGAR PINE, N30°E, 9.5' "1/4 S22 BT"</p>
<p>$\frac{1}{16}$ C S14 CORNER No. 5 LS 4753 2002 SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE NORTHWEST SLOPE, 20'± SOUTHEAST OF A ROAD. SCRIBED A 10" INCENSE CEDAR, S70 1/4°E, 14.0' "CN 1/16 S14 BT" SCRIBED AN 11" DOUGLAS FIR, S11 3/4°W, 19.9' "CN 1/16 S14 BT"</p>	<p>T21N R8E CORNER No. 10 S16 S15 S21 S22 LS 4753 2002 FD. A 3/4" IRON PIPE WITH CAP LS 2670 IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID PIPE ALONGSIDE. FD. A 49" DOUGLAS FIR STUMP WITH U.S.F.S. TAG AND PARTIAL SCAR, S15°W, 52.0' REC. A 20" DOUGLAS FIR, S10°W, 52.2' (1) FD. A 48" DOUGLAS FIR, N72°E, 27.1' - "X" IN BARK REC. A 26" DOUGLAS FIR, N70°E, 27.0' (1) SCRIBED A 6" INCENSE CEDAR, N54°W, 21.3' "T21N R8E S16 BT" SCRIBED A 6" WHITE FIR, S42°W, 7.8' "T21N R8E S21 BT" SCRIBED A 6" WHITE FIR, S50°E, 24.1' "T21N R8E S22 BT"</p>	<p>FD. A 3 1/4" ALUM. CAPPED MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A GRADUAL SOUTHWEST SLOPE IN TIMBER, 50'± NORTHEAST OF A CLEAR CUT. FD. A 25" DOUGLAS FIR, S85 1/2°E, 33.3' NO RECORD FOUND FD. A 15" WHITE FIR, N28 1/2°W, 19.5' NO RECORD FOUND FD. A DOUGLAS FIR STUMP, S32°W, 14.5' (TO FACE) REC. A 40" FIR, S30°W, 25 LKS (GLO 1884)</p>	<p>T21N R8E CORNER No. 20 $\frac{1}{4}$ S22 S23 LS 4753 2002 FD. A CAPPED PIPE IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID PIPE ALONGSIDE. CORNER FALLS ON A GENTLE EAST SLOPE IN TIMBER AND BRUSH. FD. A DEAD AND DOWN CEDAR, S64°W, 14.5' REC. AN 18" INCENSE CEDAR, S64°W, 14.5' (1) FD. A 23" INCENSE CEDAR, S75°W, 39.6' -HB REC. A 12" INCENSE CEDAR, S75°W, 39.6' (1) FD. A 27" INCENSE CEDAR, S25°E, 9.0' -HB REC. A 16" INCENSE CEDAR, S25°E, 8.6' (1)</p>	<p>T21N R8E CORNER No. 21 S20 S21 S29 S28 LS 4753 2002 FD. A 1/2" IRON PIPE WITH A 1 1/2" BRASS CAP IN A MOUND OF STONE MARKED FOR CORNER AND LS 2670. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID PIPE ALONGSIDE. CORNER FALLS ON A STEEP NORTHEAST SLOPE IN HEAVY TIMBER. FD. A 60" DOUGLAS FIR, N42°W, 11.2' -HB REC. A 48" DOUGLAS FIR, N42 1/2°W, 11.2' (1) FD. A 60" DOUGLAS FIR, N46°E, 40.3' -HB REC. A 44" DOUGLAS FIR, N46°E, 40.3' (1) FD. A 23" DOUGLAS FIR, S48°E, 18.0' -HB REC. A 14" DOUGLAS FIR, S48°E, 18.0' (1) FD. A DEAD AND DOWN FIR, S39°W, 22.5' -VS REC. A 10" DOUGLAS FIR, S39°W, 22.5' (1) SCRIBED A 13" DOUGLAS FIR, S50°W, 35.8' "T21N R8E S29 BT"</p>
<p>T21N R8E CORNER No. 6 $\frac{1}{4}$ S15 S14 LS 4753 2002 FD. A T-BAR TAGGED LS 3079 (NO RECORD) IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID T-BAR ALONGSIDE. CORNER FALLS ON A TIMBERED FLAT, 100'± EAST OF AN OLD ROAD. FD. A 24" INCENSE CEDAR, S85°W, 11.9' -VS IN OPEN SCAR NO RECORD FD. A 23" INCENSE CEDAR, S8°W, 36.4' -HB NO RECORD</p>	<p>T21N R8E CORNER No. 11 $\frac{1}{4}$ S15 S22 LS 4753 2002 NO EVIDENCE FD. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE IN SCATTERED LARGE TIMBER AND DENSE WHITETHORN BRUSH. SCRIBED A 22" WHITE FIR, N9°E, 2.0' "1/4 S15 BT" SCRIBED A 12" WHITE FIR, N67°W, 28.2' "1/4 S15 BT"</p>	<p>SET A 20" INCENSE CEDAR, N84°E, 47.3' -HB REC. A 44" INCENSE CEDAR, N85°E, 46.2' (1) FD. A 15" INCENSE CEDAR, N30°W, 19.3' -HB REC. A 18" INCENSE CEDAR, N29°W, 19.4' (1) FD. A 16" INCENSE CEDAR, S26°W, 30.1' -HB REC. AN 8" INCENSE CEDAR, S27°W, 30.0' (1) FD. A 29" WHITE FIR, S72°E, 35.6' -HB REC. AN 8" WHITE FIR, S75°E, 35.9' (1)</p>	<p>T21N R8E CORNER No. 16 $\frac{1}{16}$ C S22 LS 4753 2002 SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A SMALL MOUND OF STONE. CORNER FALLS ON A MODERATE NORTHWEST SLOPE IN TIMBER. SCRIBED A 12" WHITE FIR, S42°W, 19.6' "CN 1/16 S22 BT" SCRIBED A 5" INCENSE CEDAR, N44°W, 4.3' "X BT"</p>	<p>RECORD OF SURVEY FOR USDA FOREST SERVICE PLUMAS NATIONAL</p>