


CORNER RECORD

COUNTY OF Plumas T. 24N R. 5E M.D.B. & MERIDIAN CALIFORNIA
CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT 4/30 1981



SOUTHWEST CORNER, SECTION 36

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2-1/2" brass cap on 2" iron pipe, 0⁷ high, in rock mound stamped
U.S. General Land Office Survey T.24N. R.5E.
S35 S36
T.23N., R.5E
S1
1938

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CORNER LOCATED BY P.G.&E. SURVEY
BUT NOT VERIFIED

PACIFIC GAS AND ELECTRIC CO.
LAND DEPT. JOB LD 4840

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (include reference tie or witness points, remarks and topo of area)

points, remarks and topo of area)
FD. NO. 1 struck in 18" Dia. Fir W.Y.R.P. Stake
attached marked K.P. 12.29 SEC. COR. SOUTH
WEST COR. 36



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON FEB 11 1982 19 19
No. 3771

SIGNED:

Holey 13377

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED March 25 1982
AND EXAMINED AND FILED June 25 1982
BY: Robert S. Shultz REC 3051
TITLE: Assistant Engineer

DOCUMENT No. 27

STATEMENT ON BACK OF SHEET

002-282

YES NO