


CORNER RECORD

COUNTY OF	Plumas	T.	25 N.	R.	9 E.	M.D.B. &	MERIDIAN
CORNER TYPE	GOVT. CORNER <input checked="" type="checkbox"/>	MEANDER <input type="checkbox"/>	RANCHO <input type="checkbox"/>	CONTROL <input type="checkbox"/>	OTHER <input type="checkbox"/>	CALIFORNIA	
CORNER IDENTIFICATION — DATE OF VISIT		June 29, 1982					
		32 West $\frac{1}{4}$ corner section 32					
CORNER — LEFT AS FOUND <input checked="" type="checkbox"/>		FOUND AND TAGGED <input type="checkbox"/>		REESTABLISHED OBLITERATED CORNER <input type="checkbox"/>		REBUILT <input type="checkbox"/>	

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 3 $\frac{1}{4}$ " Brass Cap on 2 $\frac{1}{2}$ " outside diameter iron pipe stamped In Rock Mound.




PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CORNER LOCATED BY P.G.&E. SURVEY PACIFIC GAS AND ELECTRIC CO.
BUT NOT VERIFIED LAND DEPT. JOB LD 8535

CALIFORNIA COORDINATE SYSTEM ORDER:	FIRST <input type="checkbox"/>	SECOND <input type="checkbox"/>	THIRD <input type="checkbox"/>
STATIONS USED: NGS (USC & GS) <input type="checkbox"/>	STATE <input type="checkbox"/>	COUNTY <input type="checkbox"/>	STATION _____
ZONE _____	ELEVATION _____	NORTHINGS (M) _____	EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SEAL

COUNTY SURVEYOR'S CERTIFICATE	
THE CORNER RECORD WAS RECEIVED _____	
AND EXAMINED AND FILED <u>8-27</u> 19 <u>82</u>	
BY: <u>J. J. Brock</u>	
TITLE: <u>County Engineer</u>	
DOCUMENT No. <u>38</u>	
STATEMENT ON BACK OF SHEET	
YES <input type="checkbox"/> NO <input type="checkbox"/>	