


CORNER RECORD

City of _____

Document Number _____

Brief Legal Description W 1/16 COR. OF SEC. 8 & 17, T21N, R12E, MDM

County of PLUMAS, California



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

STANDARD SECTIONAL BREAKDOWN

A description of the physical condition of the monument as found and as set or reset:

SET A STD. U.S.F.S. DRIVE-IN MON. IN A STONE MOUND
(SEE BOOK 10 OF MAPS & SURVEYS PAGES 24 & 25
IN SIERRA COUNTY RECORDS)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on FEBRUARY 21, 1995.

Signed Fred W. Cook L.S. or R.C.E. Number L.S. 3966



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 2/23 1995 and examined
and filed 2/28 1995.

Signed R. Tom Shantz Title C. Surveyor



County Surveyor's Comment _____

BLAZED & SCRIBED
11" WHITE FIR
" W¹/₁₆ 58 BT"



BLAZED & SCRIBED
12" WHITE FIR
" W¹/₁₆ 517 BT"