


## CORNER RECORD

Document Number \_\_\_\_\_

Section 6, T. 25 N., R. 12 E., M.D.M.

County of Plumas, California

Brief Legal Description Parcel G, per 5 PM 76

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey September 25, 1997

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found Southwest corner of Parcel M and W.C. corner on West line of Parcel G and corners along the East Line of Parcel G as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Caps for Southwest corner and Northwest corner of Parcel G as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 25, 1997.

Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Oct 6 1997 and  
 examined and filed Nov 3 1997.

Signed R. Tom Shantz Title C.P. Surveyor

County Surveyor's Comment \_\_\_\_\_



