


CORNER RECORD

Document No. 151

Section 8, T. 22 N., R. 12 E., M.D.M.

County of Plumas, California

Brief Legal Description Lot 48, Plumas-Eureka Estates Unit No. 2, 4 M 96

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey April 30, 1998

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 1/2" rebars at radius point of Lot 50 on Madora Lake Road and Southeast corner of Lot 47 from which I reestablished the Southwest and Southeast corner of Lot 48 as shown in attached sketch.

A description of the physical condition of the monument as found and as set or reset: Found 1/2" rebars at radius point of Lot 50 on Madora Lake Road and at Southeast corner of Lot 47, Set 5/8" rebar with Plastic Cap stamped LS 2843 at Southwest and Southeast corner of Lot 48 as shown in attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 1, 1998.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 5/7 1998 and
 examined and filed 5/22 1998.


Signed R. Tom Shultz Title C. Surveyor



County Surveyor's Comment _____



50 25 0 50
1"=50'



Lot 48
Plumas-Eureka Estates
Unit No. 2, 4 M 96

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571