


CORNER RECORD

Document Number _____

Section 25, T. 22 N., R. 12 E., M.D.M.

County of Plumas

, California

Brief Legal Description Lot shown between Upper Main Street and County Road 115
with deed reference 218 O.R. 108

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Feb. 7, 2000

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 3/4" I.P. tagged RE 7294 at Southwest corner Block 3, found 5/8" rebar with
Aluminum Cap stamped LS 2843 at Southeast corner Block 3, found 5/8" rebar with
Aluminum Cap stamped LS 2843 on East side of portion between Upper Main Street and
County Road 115 with deed reference 218 O.R. 108 in record position from which I
established the Northwest and Southwest corners of said portion per 9 RS 126.

A description of the physical condition of the monument as found and as set or reset: Set tag LS 2843 in rock
in concrete base near pipe fence post at Northwest corner, set 5/8" rebar with Aluminum
Cap stamped LS 2843 at Southwest corner of Lot in record position per 9 RS 126.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on February 7, 2000.


Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3/2 2000 and
 examined and filed 3/20 2000.

Signed Tom Shultz Title Co Surveyor



County Surveyor's Comment _____



1" = 50'

Block 3
9 RS 126 & 127

Found 5/8" rebar
with Aluminum Cap
stamped LS 2843
per 9 RS 126

Railway
Street

Found 3/4" I.P.
tagged LS 7294
per 9 RS 126

S78°45'12"W

300.00'

Upper Main Street

Set tag LS 2843 in lead with
nail in rock in concrete base
near pipe fence post

S78°45'12"W
200.00'

N78°45'12"E
50.00'

Found 5/8" rebar
with Aluminum Cap
stamped LS 2843
per 9 RS 126

Spruce
Street

S11°14'48"E
60.00'

S78°45'12"W
100.00'

218 O.R. 108

Set 5/8" rebar with Aluminum
Cap stamped LS 2843

N78°45'12"E
180.19'

County Road 115, Clio State 40A Road

00009