

## CORNER RECORD

Document Number


232

NE1/4 SECTION 17, T 22 N, R 13 E., M.D.M.

County of PLUMAS

, California

Brief Legal Description PARCEL 2 OF 12 RS 108 AND PARCEL 3 OF 1 PM 78



## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey FEB. 14, 2003.

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown and described on attached sketch and as shown on 1 PM 78 AND 12 RS 108.

A description of the physical condition of the monument as found and as set or reset:

Found points as described and in good condition. Points set as shown on attached sketch, as witness corner to actual property corner, which falls in river.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 2, 2003.

Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 4-29 2003 and  
 examined and filed May 6 2003.

Signed R. Tom Shute Title Plumas County Surveyor



County Surveyor's Comment \_\_\_\_\_

NOTE: ALL DISTANCES ARE RECORD PER 1 PM 78  
AND 12 RS 108



## LEGEND

- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843 as Witness Corner, (Actual Corner falls in River)

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571