

CORNER RECORD

Document Nu


270

Portion Section 8, T.23N.R.14E.,MDM

County of Plumas

,California

Brief Legal Description Lot 60 Welch Estates Unit No. 1 per 2 M 11



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey AUGUST 30, 2004

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found corners indicated on attached sketch in good condition and in proper location except the Southwest corner of Lot 60 which was out of the ground. We reset it with a 5/8" rebar with aluminum cap stamped LS 2843, in record position.

A description of the physical condition of the monument as found and as set or reset:
see statement above.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 30, 2004.


Signed John W Hamby L.S. 2843
John W. Hamby



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 9/22 2004 and
examined and filed 10/4 2004

Signed R Tom Stanton Title _____



County Surveyor's Comment _____

- FOUND 3/4" I.P. open , 2 M 11 shows 1/2 in to be set
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Found 1 1/2" I.P. open per 2 M 11-13
- Nothing found or set
- (M) Measured
- (R1) RECORD per 2 M 11



LOT 60 Welch Estates No. 1
Book 2 Maps page 11
Plumas County, Ca.
Scale 1" = 50'
August, 2004

04242

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571