


## CORNER RECORD

Document Number 272

Portion Section 12, T.23N.R.13E. MDM

County of Plumas, California

Brief Legal Description Portion Lot 24, Grizzly Creek Retreat per Book 3 M 84



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey Sept, 20, 2004

Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found front corners shown on attached sketch in proper locations and in good condition.

A description of the physical condition of the monument as found and as set or reset:

Reset front corners of Lot 24 as shown on the attached sketch. Set 5/8" rebar with aluminum cap

stamped LS 2843.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept. 20, 2004.

Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Oct 4<sup>th</sup> 2004 and  
examined and filed Nov. 2<sup>nd</sup> 2004.Signed R. Tom Spurter Title R.C.E. 30515

County Surveyor's Comment \_\_\_\_\_


- FOUND 1/2" i.p. tagged LS 2702 per 3 M 84.

- SET 5/8" Rebar & Aluminum Cap LS 2843

(R1) RECORD per 3 M 84

- Nothing found or set

(M) Measured



Portion Lot 24  
GRIZZLY CREEK RETREAT  
3 M 84  
Plumas County, Ca.  
Scale 1"=50'  
Sept. 2004

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571

04278