

CORNER RECORD

Document Number


273

Portion Sec. 35T.23 N.R.13E. MDM

County of Plumas

, California

Brief Legal Description Lots 17,18,19 ,20 & 21, Block 11 West Portola, per Book A Maps, 26



CORNER TYPE

Government Corner Control

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Sept. 1, 2004

Elev. _____

COORDINATES
(Optional)Corner— Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found points shown on attached sketch in good condition, and in proper locations.

Set points shown in record locations per A Maps 26.

A description of the physical condition of the monument as found and as set or reset:
see above.

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on Sept. 23, 2004.Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10/14 2004 and
examined and filed Nov. 2nd 2004.Signed R. Tom Shuster Title R.C.E. 30515

County Surveyor's Comment _____

- FOUND point as described
- FOUND Rebar with Aluminum Cap LS 2843 per (R2) or as noted
- SET 5/8" Rebar & Aluminum Cap LS 2843
- FOUND 3/4" IP tagged LS 3297 per 4 PM 92
- (R1) RECORD per 4 PM 92
- (R2) RECORD per A Maps 26
- (M) Measured



04102

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571