

CORNER RECORD


Document Number

279

Portion Section 36, T23N.R.13E. MDM

County of Plumas, California

Brief Legal Description Lots 2 & 3 Block 20, Northern Addition to Portola, Book A page 32



CORNER TYPE

Government Corner Control

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey _____

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
 Found points as indicated on attached sketch. Two points, not of record were in positions shown. SW corner of Block was destroyed by fence construction and was replaced as indicated in position shown on 9 PM 8.

A description of the physical condition of the monument as found and as set or reset:
 All found monuments, except those mentioned above were in good condition.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Nov. 8, 2004.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Nov. 18th, 2004 and
 examined and filed 1/11 2005 2004.


Signed R. Tom Stantis Title Plumas Co.
Engineer



County Surveyor's Comment _____

LEGEND

- FOUND Rebar with Plastic Cap LS 2843
- SET 5/8" Rebar & Aluminum Cap LS 2843
- ☒ FOUND Rebar with Aluminum Cap LS 2843 per 9 PM 8
- (R1) RECORD per 9 PM 8
- (R2) RECORD per A RM 32.
- (M) Measured



Portion of Block 20
Northern Addition to Portola

Portola - Plumas County - Calif.
Scale 1"=100' November 2004

04238

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571