


CORNER RECORD

Document Number 291

Portion Section 36, T.23N.R.13E. M.D.M.

County of Plumas, CaliforniaBrief Legal Description Lots 1 & 2 Block 3, Northern Addition to Portola Townsite Maps 32.

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey June 30, 2004

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found corners indicated in good condition.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with aluminum cap stamped LS 2843 at locations indicated on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 30, 2004.


Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 8th 2005 and
examined and filed May 31, 2005.Signed R. Tom Stanton Title Engineer

County Surveyor's Comment _____

- FOUND point as described NOT OF RECORD
- FOUND open 3/4" I.P. not of record
 - SET 5/8" Rebar & Plastic Cap LS 2843
- (R1) A Maps 32.
- (M) Measured



PORTION BLOCK 3
NORTHERN ADD. TO PORTOLA TOWNSITE

R.M. A PAGE 32

PORTOLA PLUMAS COUNTY CALIF.
SCALE 1"=100' JULY, 2004

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571