

## CORNER RECORD

Document Number


297

Portion Sec. 33, T.24N.R.11E. MDM

County of Plumas

, California

Brief Legal Description Lot 150 Greenhorn Ranch Sub. No.2 per 4 M 14



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey April, 30, 2004

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points indicated in good condition and in proper locations. Points search for had been destroyed by utility company and driveway construction.

A description of the physical condition of the monument as found and as set or reset:

Set points as indicated on attached drawing.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 30, 2004.

Signed John W. Hamby L.S. 2843  
John W. Hamby



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 8<sup>th</sup> 2005 and  
examined and filed May 31, 2005


Signed R Tom Stanton Title Engineer



County Surveyor's Comment \_\_\_\_\_

- FOUND 1" I.P. tagged RCE 11585 per 4 M 18.
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Searched for, not found

(R1) RECORD per 4 m 14



LOT 150  
GREENAHORN RANCH SUB. No. 2  
4 M 14

Sec. 33 T 24N.R11E. M.D.M  
Plumas County, Calif.  
Scale 1"=60' May, 2004

04091

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571