


CORNER RECORD

Document Number 354

Section 25, T. 22 N., R. 12 E., M.D.M.

County of Plumas, CaliforniaBrief Legal Description Corner between 4.04 ac. & 7.91 ac Parcels per 9 RS 126

CORNER TYPE

Government Corner Control COORDINATES
(Optional)Meander Property

N. _____

Rancho Other

E. _____

Date of Survey 7-20-07

Zone _____ Datum _____

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Northwest corner of 4.04 acre parcel and South West corner of 7.91 acre parcel
which is also CN 1/16 per 9 RS 126 and shown on attached sketch.A description of the physical condition of the monument as found and as set or reset: Set common corner to
4.04 acre parcel and 7.91 acre parcel in record position on West side of parcels as
shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on August 17, 2007.Signed John L. Owen L.S. 5620
John L. Owen

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Oct. 25th 2007 and
examined and filed Oct 30th 2007.Signed R. Tom Shunter Title County Surveyor

County Surveyor's Comment _____

