

## CORNER RECORD

Document Number

366

A portion of Section 16, T. 23 N., R. 14 E.

County of Plumas

, California

Brief Legal Description Lot 22, Grizzly Ranch Unit 1, 9 M 92

	X

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey November 8, 2007

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
 Found points shown on attached sketch in condition shown per 9 M 92.

A description of the physical condition of the monument as found and as set or reset:  
 Set 5/8" Rebar with Aluminum Cap LS 5620 in record position shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in  
 conformance with the Land Surveyors' Act on November 9, 2007.


Signed John L. Owen L.S. 5620  
 John L. Owen




## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Feb 19<sup>th</sup> 2008 and  
 examined and filed 3/10/08 2008.

Signed R. Tom Hunter Title County Surveyor



County Surveyor's Comment \_\_\_\_\_



Bearings and Distances shown hereon  
are Record and Measured per 9 M 92.

