

CORNER RECORD

Document Number

381

S. 36, T. 23N, R. 13E, M.D.M.


County of Plumas

, California

Brief Legal Description

Lots 22, 23 & 24 in Block 8

Northern Addition to Portola Townsite, Book "A" Maps 32



CORNER TYPE

Government Corner Control COORDINATES
(Optional)Meander Property

N. _____

Rancho Other

E. _____

Date of Survey March 15, 2010

Zone _____ Datum _____

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found corners shown on 15 RS 21 in good condition as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Set Easterly corners of Lot 24 in Block 8, 5/8" rebar with Aluminum Cap LS 5620
in record position shown on 15 RS 21 as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on March 15, 2010.Signed John L. Owen L.S. 5260
John L. Owen

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 1, 2010 and
examined and filed June 14, 2010.Signed R. Tom Shumate Title County Surveyor

County Surveyor's Comment _____

Basis of Bearings

The Basis of Bearings of this map is identical to that shown in Book 15 of Record of Surveys at Page 21, Plumas County records.

Bearings and Distances are Record and Measured per 15 RS 21

Found 1/2"
I.P. N 11°14'33"
W. 0.20' from
set position

N67°08'09"E 60.00'

Found 5/8" Rebar w/ Aluminum
Cap LS 5620 per 15 RS 21.

