


CORNER RECORD

Document Number 382

S. 8, T. 23 N., R. 14 E. MDM County of Plumas, California
 Brief Legal Description Lot 62, Welch Estates Unit 1, 2 M 11



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey July 7, 2010

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 3/4" Iron Pipe, no tag, at Northwest corner of Lot 62 and at 2 points of reverse curve of Cul-de-sac
 in good condition as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with Aluminum Cap LS 5620 for most northerly corner of Lot 62 as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
 conformance with the Land Surveyors' Act on July 12, 2010.

Signed John L. Owen L.S. 5620
 John L. Owen



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 7 2010 and
 examined and filed August 9 2010.

Signed R. Tom Hunter Title County Surveyor



County Surveyor's Comment _____

LEGEND

- FOUND 3/4" Iron Pipe, no tag shown as 1/2" IP per (R1)
- SET 5/8" Rebar with Aluminum Cap LS 5620 (R1) RECORD per 2 maps 11

Bearings and Distances are Record and Measured per 2 M 11.

