


CORNER RECORD

Document Number 383

S. 22, T. 22 N., R. 12 E. MDM

County of Plumas

, California

Brief Legal Description Lot 119, Graeagle Subdivision No. 5, 3 M 102

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey June 8, 2010

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/2" rebar, no tag, at Southwest corner of Lot 119 and beginning of curve of Lot 118 in good condition.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with Aluminum Cap LS 5620 for Northwest corner of Lot 119 as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 8, 2010.

Signed John L. Owen L.S. 5620
 John L. Owen



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept 22 2010 and examined and filed September 28 2010.

Signed R. Tom Skarster Title County Surveyor



County Surveyor's Comment _____

LEGEND

- FOUND 1/2" Rebar, no tag (R1)
- SET 5/8" Rebar with Aluminum Cap LS 5620
- (R1) RECORD per 3 maps 102

Yonkalla Trail

N04°23'40"E
110.00'

Lot 118

Bearings and Distances are Record
and Measured per 3 M 102.

N04°23'40"E
114.34'

Lot 119

