

# CORNER RECORD


City of near Whitehawk

Agency Index 432

Document Number \_\_\_\_\_

County of Plumas, California

Brief Legal Description Center West Southwest 1/64th, S1, T21N, R12E Mount Diablo Meridian



## CORNER TYPE

Government Corner  Control  
 Meander  Property  
 Rancho  Other

## COORDINATES (Optional )

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units Metric  U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

Date of Survey 9-29-2018

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref:  8765(d)  8771  8773  Other:

Corner/  Left as found  Established  Rebuilt  Pre-Construction  
 Monument:  Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):

Found  $\frac{5}{8}$ " Aluminum Rod with  $3\frac{1}{4}$ " Aluminum Cap in rock mound, per 9RS107.

Monument in excellent condition. Rebuilt and added to rock mound, 3' diameter, 6" in height.

Set new bearing tree. Painted rocks red. Set post with 54-2 & 54-9 sign 2' southwesterly.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on 11/29/18

Signed ALAN D. FRANK P.L.S. or R.C.E. No. P.L.S. 7172



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2/29/19

and examined and filed 7/30/19

Signed R. Tom Hunter P.L.S. or R.C.E. No. 30515

Title County Surveyor



County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_

T21N R12E  
S 1/16  
S2 S1  
LS5623  
1989

684.89' MEASURED AND  
RECORD PER 9RS107

S1  
C-W-SW  
1/64  
LS5623  
1989

S 45°48' W  
11.9'

S 37°06' E  
40.9' (41.4')

Set new bearing tree, a  
29" White Fir, blazed and  
scribed "XBT", etched 6"  
ring 6' above ground,  
painted blaze and ring red.  
54-3 sign. Mag Spikes for  
bearing and distance.  
54-9 sign on back of tree.

Refreshed and Repainted  
a 13" White Fir, painted blaze  
and ring. Mag Spikes for bearing  
and distance. 54-9 sign on  
back of tree.

( ) INDICATES RECORD  
DATA PER 9RS107



The Southwest-Southwest 1/64 Witness Corner  
of Section 1 was destroyed and has  
not been reestablished hereon.

NOT TO SCALE