


# CORNER RECORD

COUNTY OF Plumas T. 24 N. R. 9 E. M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT June 9, 19 82



Northwest corner section 4

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 3 1/4" outside diameter Brass Cap on 2" outside diameter Iron Pipe stamped.




PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CORNER LOCATED BY P.G.&E. SURVYOR PACIFIC GAS AND ELECTRIC CO.  
BUT NOT VERIFIED LAND DEPT. JOB LD4535

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NOS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (N) \_\_\_\_\_ EASTINGS (E) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)



**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON No. 3771 June 18 19 82

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No. LSU 3771

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED July 1 19 82 AND EXAMINED AND FILED July 19 82

BY: R. Tom Hunter R1E 30513

TITLE: Assistant Engineer

DOCUMENT No. 29

STATEMENT ON BACK OF SHEET

YES  NO