


CORNER RECORD

COUNTY OF PLUMAS T. 25N R. 11E MDM MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER HES 262

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER 2 HES 262

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

RECORD: 2" dia I.P. over marked stone w/brass cap MARKED 2 HES 262

A PINE 6" dia. bears S 34° 38' E, 41 LKS. dist. marked 2 HES 262 B.T.

A PINE 14" dia bears S 87° 38' W 62 LKS dist. marked 2 HES 262 B.T.

FOUND: 2" dia I.P. 16" above ground in 24" MAS. w/2 1/2" brass cap MARKED: →

An 8" PINE w/ROTTED HEARTWOOD 6 ft+ high Bears S 88° W 62 LKS; un readable scribe remnant alongside



PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

NEW B.T.'s: 8" dia. CEDAR S 17° W 9.6 LKS MKD: 2 HES 262 B.T.

4" Fir S 64° W 8.6 LKS MKD: "X", "BT"

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

SURVEYOR'S CERTIFICATE


THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

ON 6-12 1985

SIGNED: Robert Cranberry

L.S. or R.C.E. No.: LS5287

SEAL



COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED 3-6 1986

BY: Tom Spinto

TITLE: Asst Engineer

DOCUMENT No. 45

STATEMENT ON BACK OF SHEET

YES NO