


CORNER RECORD

COUNTY OF Plumas T. 25N R. 11E MDM MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER HES 262
 CORNER IDENTIFICATION — DATE OF VISIT 4-30 19 85



CORNER 3 HES 262

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

RECORD: 2" dia I.P. in Mos over a marked STONE, w/brass CAP MKD. 3 HES 262
 A Pine 18" dia bears S 18° 48' E, 35 LKS dist. MARKED: 3 HES 262 B.T.
 A Pine 5" dia bears N 1° 59' W, 69 LKS dist MKD: 3 HES 262 B.T.
Found: 22 1/2" P. Pine Magnetic bearing S 19° E 35 LKS closed blaze



2" dia I.P. extending 7" above Ground in Toe of fill of Road; w/2 1/2" brass Cap marked as above

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

NEW B.T. : 7" Ponderosa Pine N 19° E 21.8 LKS MARKED: 3 HES 262 BT

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 6-12 19 85

SIGNED Robert Cranberry
 L.S. or R.C.E. No.: LS 5287 L.S. 6287



COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED 3-6 19 86

BY: Tom Smith
 TITLE: Asst. Engineer

DOCUMENT No. 46

STATEMENT ON BACK OF SHEET

YES NO