


COUNTY OF Plumas T. 25 N R. 11 E M & M MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER HES 262

CORNER IDENTIFICATION — DATE OF VISIT 4-30 19 85



Corner #4 HES 262

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Record: 24"x10"x6" stone mkd "4 HES 262

from which bears:

8" Pine S 85° 53' E 121 ks mkd "4 HES 262 BT"

Found: 10"x6" stone, extending 15' above ground, mkd "4 HES 262", in 48" M.O.S.

from which bears: 12" P. Pine S 86° E 121 ks w/ ^{partially} healed blaze & illegible scribing visible

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

New BT: 10" P. Pine S 81° E 11.5 ks mkd "4 HES 262 BT"

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (include reference tie or witness points, remarks and topo of area)

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 6-12 19 85

SIGNED: Robert Cranberry
L.S. or R.C.E. No.: LS 5287



COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED 3-C 19 86

BY: Tom Smith
TITLE: Asst. Engineer

DOCUMENT No. 47

STATEMENT ON BACK OF SHEET YES NO