


COUNTY OF Plumas T. 25 N R. 11 E 11 DM MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER HES 262 #6
CORNER IDENTIFICATION — DATE OF VISIT 4-30 19 85



#5 HES 262

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
Record: 2" I.P. over mkd stone w/ brass cap mkd "6 HES 262"
from which bears: 6" black oak S50°43'W 31 lks mkd "6 HES 262 BT"
16" Fir N 23°06'W 38 lks mkd "6 HES 262 BT"
Found: 2" I.P., extending 24" above ground, w/ brass cap mkd "6 HES 262"
from which bears: 17" Black oak S51°W 31 lks w/ heated blaze
38" Fir stump (24" high) w/ scribed remnant
N23°W 39 lks

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

New BT: 5" D. Fir S11°W 11.7 lks mkd "6 HES 262 BT"

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 6-12 19 85

SIGNED: Robert Geranberg

L.S. or R.C.E. No.: LS 5287



COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED 3-6 19 86

BY: Tom Smith
TITLE: Asst. Engineer

DOCUMENT No. 49

STATEMENT ON BACK OF SHEET YES NO