


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description T 22N - R 9E (8 RS 90)



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey MAY 1992

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND A 20" x 12" x 12" STONE MARKED "1A" ON THE WEST FACE
AND A 38" RED FIR 54 1/2° E, 196 68' (RECORD 20" FIR 54 1/2° E 196 68')

A description of the physical condition of the monument as found and as set or reset:

SET IN PLACE OF THE STONE IS A 3 1/4" ALUMINUM CAP ON A 5/8" STEEL
ROD, FROM WHICH: A 12" CEDAR SCRIBED "1A 516 BT" BEARS 534° W, 8 3/4'
AND AN 8" WHITE FIR SCRIBED "1A 515 BT" BEARS 568° E, 9 3/4'

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 12 1992.

Signed Fred W. Cook L.S. or R.C.E. Number LS 4966



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 15 1992 and examined and filed JUNE 16 1992.

Signed R. Tom Hunter Title County Surveyor



County Surveyor's Comment _____

516 515

