
CORNER RECOR	Document umber	245
Portion N.E. 1/4 Sec. 36, 1.23N.R.13E. MDM		,Californic
Brief Legal Description Lots 21,22,23,24, Block 3		
├── Meander □ F	Control □ Property 🛭	COORDINATES (Optional) N E
Rancho Date of Survey August 28	Other □ , 2003	ZoneDatum Elev
Corner— Left as found □ Found and tagged	□ Established □ [Reestablished 🛛 Rebuilt 🛭
Identification and type of corner found: Evidence used to ide Found points as indicated on attached sketch.	ntify or procedure used to	establish or reestablish the corner
A description of the physical condition of the monument as for on the attached sketch were in good condition.	ound and as set or reset:	
SURVEYOR'S STATE	MENT	JOHN W. HAMBY
This Corner Record was prepared by me or a conformance with the Land Surveyors' Act or Signed John W. Hamby	ınder my direction in 1 Sept. 2, 2003.	JOHN W. HAMBY (C) (Exp. 6-30-04) (C) (LS. 2843) (C) (CALIFORNIA)
COUNTY SURVEYOR	'S STATEMENT	PROFESS/OA
This Corner Record was received Septemb	er 3 2003 and	No. 30515 Fyn 3/31/04/ RESSIONAL TO REPORT TO HUNDER PORT TO PROFESSIONAL TO
examined and filed <u>September 18</u> 2003 Signed <u>R Jam Shunth</u> Title	3.	No. 30515 Exp3/31/04
Signed R Jam Stanta Title	<u>Plunas Co. Surveyor</u>	CML CML *
County Surveyor's Comment		· CALI

FOUND Rebar with Alumi 1 Cap LS 5620
FOUND point as describe.
○ SET 5/8" Rebar & Aluminum Cap LS 2843
(R1) Record per Book A page 32.



Scale 1" = 100'



PORTION BLOCK 3 NORTHERN ADD. TO PORTOLA

R.M. Book A, page 32

Portola Plumas County Calif.
Scale 1" = 100' September, 2003

Hamby Surveying Inc. P.O. Box 1209 Portolo, CA 96122 (530) 832-5571