


CORNER RECORD

Document Number 322

IN THE SW1/4 OF SEC. 6, T24N, R15E, MDM County of PLUMAS, California

Brief Legal Description LOT 8 DIXIE VALLEY PROPERTIES UNIT 1



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey NOVEMBER 16, 2005

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND MONUMENTS INDICATED ON ATTACHED SKETCH IN GOOD CONDITION AND IN RECORD POSITION. AND ACCEPTED.
PER 4 M 12. MONUMENTS FOUND WERE OF DIFFERENT CHARACTER AND HAD DIFFERENT "LS" NUMBER THAN 4 M 12.

A description of the physical condition of the monument as found and as set or reset: _____
SET 5/8" REBAR WITH ALUMINUM CAP STAMPED LS 5620 AT LOCATION FOR MISSING CORNERS AS SHOWN
ON ATTACHED SKETCH.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 30, 2005.

Signed John L. Owen L.S. 5620
John L. Owen



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Jan 12th 2006 and examined and filed 3/13/06 2006.

Signed R. Tom Hunter Title County Surveyor



County Surveyor's Comment _____

Found a 5/8" Rebar
and Plastic Cap
PLS 2469
No Record

Found a 5/8" Rebar
and Plastic Cap
LS 2469
No Record

DIXIE VALLEY ROAD

LOT 8
4 M 12

R = 2283'
N73°40'36"W
168.10'
(R1)(M)

R = 2283'
N79°27'36"W
292.54'
(R1)(M)

N83°08'00"W
128.12'
(R1)(M)

N83°08'00"W
90.00'
(R1)(M)

N50°55'59"E
230.00' (R1)(M)

N71°34'00"W
69.18'
(R1)(M)



1" = 100'

LEGEND

- FOUND Monument as described
- SET 5/8" Rebar & Aluminum Cap LS 5620
- (R1) RECORD per 4 M 12 (Grid)
- (M) MEASURED

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571