


# CORNER RECORD

Agency Index 436  
 Document Number \_\_\_\_\_

City of near Whitehawk County of Plumas, California  
 Brief Legal Description Southeast Southwest 1/64th, S1, T21N, R12E Mount Diablo Meridian



### CORNER TYPE

Government Corner  Control  
 Meander  Property  
 Rancho  Other

Date of Survey 10-9-2018

### COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Units Metric  U.S. Survey Foot   
 Horizontal Datum \_\_\_\_\_  
 Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
 Vertical Datum \_\_\_\_\_  
 Complies with Public Resources Code §§8801-8819  
 Complies with Public Resources Code §§8890-8902

PLS Act Ref:  8765(d)  8771  8773  Other:  
 Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:  
 See sheet #2 for description (s):

Found  $\frac{5}{8}$ " Aluminum Rod with  $\frac{3}{4}$ " Aluminum Cap in rock mound, per 9RS107.

Monument in excellent condition. Rebuilt and added to rock mound, 3' diameter, 6" in height.  
 Set new bearing tree. Painted rocks red. Set post with 54-2 & 54-9 sign 2' southeasterly.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Professional Land Surveyors' Act on 11/29/18  
 Signed [Signature] P.L.S. or R.C.E. No. P.L.S. 7172



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7/27/19  
 and examined and filed 7/30/19  
 Signed R. Tom Hunter P.L.S. or R.C.E. No. 30515  
 Title County Surveyor



County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

