

- LEGEND**
- Found monument as noted
 - Set 1/2" rebar RCE 22836
 - (-A) Record per 1 RS 131
 - (-B) " " 090 OR 206
 - (-C) " " 1 RS 105
 - (-D) " " 292 OR 085
 - (-E) " " 6 PM 13
 - (-F) " " 176 OR 785
 - (-G) " " 338 OR 472
 - (-H) " " 119 OR 102
 - (-I) " " 276 OR 294
 - △ Computed corner

* Distances measured to lines of possession shown for information only - no monuments found or set


Inner edge of sidewalk held for line of ROW at this point per -A. No monuments found this area- appear to have been destroyed by retaining wall & driveway construction

1/4 Corner 3/2 per -A,C,E
Axle with gears up. Set tag RCE 22836
N89°49'42"E 20.64'
N89°32'22"E 30.18'

SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors Act at the request of Maude Quintana in June 1984.

Clifford R. Brown
Clifford R. Brown RCE 22836



COUNTY SURVEYOR'S CERTIFICATE

This map has been examined for conformance with the requirements of the Land Surveyors Act this ___ day of ___ 1984.

Lawrence J. Brock
Lawrence J. Brock, RCE 13528
Plumas County Surveyor

COUNTY RECORDER'S CERTIFICATE

Filed this 24th day of August 1984, at 12:45 P.M. in Book 6 of Record of Survey at page 142 at the request of the County Engineer.

Fee \$5.00

Ila Diggs, Plumas County Recorder

File No. 1350

by *Patricia Lopez*
deputy

RECORD OF SURVEY
for
MAUDE QUINTANA

A Portion of Sections 2 and 3, T26N, R9E, MDB&M
Greenville, Plumas County, California

Clifford R. Brown Engineering & Surveying
Rt 1 Box 480B
Quincy, Calif.

July 1984

sheet 1 of 1

db