



Legend:
 ○ = Set $\frac{1}{2}$ " rebar with aluminum cap, LS 2843
 ● = Found $\frac{1}{2}$ " rebar & cap, LS 2843, or as noted
 (R) = Record
 (M) = Measured

Note:
 This map shows the change in the line between Parcels 1 and 2 of 7 PM 79

All measurements are record and measured unless otherwise noted.

RECORD OF SURVEY

FOR
 Robert Pitzer

In the S.E. 1/4 of Sec. 26 and the N.E. 1/4 of Sec. 35, T. 23 N.,
 R. 13 E., M.D.B. & M., Plumas County, California

SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors Act at the request of Robert Pitzer on June 4, 1981.

John W. Hamby
 John W. Hamby LS 2843

COUNTY SURVEYOR'S CERTIFICATE

This map has been examined for conformance with requirements of the Land Surveyors Act this 3rd day of August, 1981

Lawrence J. Brock
 Lawrence J. Brock RCE 13528
 Plumas County Surveyor

RECORDER'S CERTIFICATE

Filed this 6 day of August, 1981 at 3:51 P.M. in Book 6
 of Records of Surveys at Page 11 at the request of the
 County Engineer

Ila Diggs
 Plumas County

Fee \$5.00
 File No 1008

by *Jacqueline Andrew*
 Deputy

Hamby Surveying, Inc., LS 2843

Paradise, California
 P.O. Box H.H.
 (916) 877-6253

Portola, California
 P.O. Box 842
 (916) 832-5571