



**BEARING TREES (BEARS FROM CORNER)**

- (A) 8" PINE - S49°E 20.2'  
6" FIR - S5°W 24.4'
- (B) 4" FIR - S62°W 3.6'  
8" FIR - N54°W 8.1'
- (C) 7" PINE - SOUTH 25.6'  
7" FIR - N23°W 35.9'
- (D) 12" PINE - N73°W 16.0'  
12" OAK - S16°W 6.0'  
12" PINE - S90°E 28.2'  
7" FIR - N35°E 21.5'

**LEGEND**

- ▲ FOUND STANDARD B.L.M. MONUMENT AND BRASS CAP W/ BEARING TREES MKD. AS NOTED, 2" IRON PIPE W/ 3" B.C.
- SET STANDARD 2" ALUM. PIPE W/ MAGNETIC BASE AND 3" ALUM. CAP MKD. AS NOTED, LS4388
- FOUND 1" IRON PIN W/ 2 1/2" ALUM. CAP MKD. AS NOTED
- [ ] G.L.O. CALLS, DISTANCES CONVERTED FROM CHAINS TO FEET
- (-) CALCULATED BEARING AND DIST. FOR SECTIONAL BREAKDOWN
- FOREST SERVICE ROAD
- PROPERTY LINE MARKED AND POSTED

**RECORD OF SURVEY**  
FOR  
UNITED STATES FOREST SERVICE  
PLUMAS NATIONAL FOREST

IN SEC. 29 AND 33, T26N, R9E, AND SEC. 4, 6, AND 9,  
T25N, R9E, M.D.M.,

**PAYNE SURVEYING**  
2946 INEZ STREET  
REDDING, CA. 96001  
PHONE 916-243-1730  
DATE OCTOBER 1979 SCALE 1"=400' SHEET 2 OF 7