


Basis Of Bearings:
 The North line of Section 2, shown as N 88° 35' 17" E on the map filed in book 5 of Records of Surveys at Page 16, Plumas County Records.

Legend:
 O: Set 1/2" rebar with aluminum cap, LS 2843
 ●: Found point as noted.
 (R): Record
 (M): Measured



SCALE: 1"=200'

RECORD OF SURVEY
 FOR
City of Portola

In the N.W. 1/4 of Sec. 2, T. 22 N., R. 13 E., M.D.B. & M.
 Portola, Plumas County, California

SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors Act at the request of City of Portola on Apr. 21, 1982.

John W. Hamby
 John W. Hamby LS 2843

COUNTY SURVEYOR'S CERTIFICATE

This map has been examined for conformance with requirements of the Land Surveyors Act this 21st day of January, 1982.

Lawrence J. Brock
 Lawrence J. Brock RCE 13528
 Plumas County Surveyor

RECORDERS CERTIFICATE

Filed this 21st day of January, 1982, at 3:05 p.m. in Book 6 of Records of Surveys at Page 44 at the request of the County Engineer.

Fee \$ 5.00
 Ila Diggs
 Plumas County Recorder

File No. 6013
 by *Isabelle Andrews*
 Deputy

Hamby Surveying, Inc., LS 2843
 Paradise, California
 P.O. Box H.H.
 (916) 877-6253

Portola, California
 P.O. Box 842
 (916) 832-5571

Sheet 1 of 1

BRUNING 44-132 40893