



LEGEND

- CORNER FOUND as noted
- CORNER SET as noted
- PROPERTY BOUNDARY blazed and posted.
- - - DIMENSION LINE
- (S) GLO DATA
- [] DATA per 3 RS 144
- ① KEY TO CORNER NOTES

GENERAL NOTES

1. Monuments set on this survey were supplied by the U.S.F.S. They are 3" caps on 2" pipe, manufactured of aluminum. The corner identification was stamped on the cap as per the 1973 BLM "Manual of Instructions".
2. Trees marked as accessories to corner monuments were scribed to conform to BLM practice.

CORNER NOTES

- ① ^{24/19}/_{25/30} Fd. 1/2" iron pipe tagged R.C.E. 13528, GLO BT.: D. Fir stump N.68 1/2° E. 56.1' [N.71°19'E. 58.2'] per 3RS144. Set monument stamped LS 3621 and marked new B.T.'s: 5 1/2" Fir S.45°W. 21.8', 5 1/2" Fir N.35°W. 18.3', 5 1/2" Cedar N.62°E. 10.2', 16" Fir S.85°E. 4.1' Set pipe alongside.
- ② ^{19/20}/_{24/29} Fd. 1/2" I.P. R.C.E. 13528 per 3RS 144, GLO B.T.'s: Pine stump N.20 3/4° E. 33.7' [N.19°22'E. 31.7'], 8" B.Oak snag N.66°W. 40.9' [N.66°30'W. 43.3'] Set pipe alongside. Set mon. stamped LS 3621 and marked new B.T.'s: 13" Fir S.54°W. 10.2', 11" Fir S.75°E. 16.4', 6" Fir N.13°W. 24.8'
- ③ ^{30/29}/_{31/32} Fd. 1" I.P. w/plastic plug LS 3208 not of record. Fd. GLO BT.'s: 7" Fir (dead & down) S.49°W. 17.8', Oak stumphole S.30°E. 11.2'. Replaced pipe with mon. stamped LS 3621 and marked new B.T.'s: 11" B.Oak S.45°E. 49.9', 11" Fir S.87°W. 25.0'
- ④ ^{30/29}/_{31/32} Fd. 1971 B.L.M. brass cap mon. and B.T.'s: 10" Fir N.16°E. 27.7', 12" Fir S.80°E. 19.8', 9" Fir S.15°W. 26.4' Fd. orig B.T.: 52" Fir S.36°W. 45.5'

SURVEY HISTORY

1871: A.W. KEDDIE surveys north and west lines and northwest 1/4 of sec. 30.
 1880: W. MINTO surveys remainder of sec. 30.
 Recovery of original corner evidence has been made through the years by private surveyors and government employees.
 No new corner evidence was recovered by this survey.

- ⑤ ^{4/36}/₃₁ Fd. orig. B.T.: 48" Fir N.44°W. 70.0' Set mon. stamped L.S.3621 and marked new B.T.'s: 13" Fir S.1°E. 3.1', 8" Fir N.27°W. 11.2'
- ⑥ ^{4/36}/₃₁ Orig. evidence not fd. Set mon. stamped L.S. 3621 W.C. as witness corner S.89°27'41"E. 9.0' from true prorate position (See detail) Mk'd new B.T.'s: 16" Fir S.37°E. 55.5', 7" Fir N.48°E. 24.5'
- ⑦ ^{1/25}/₃₀ Set mon. at prorate position and marked new B.T.'s: 13" Fir S.36°E. 9.7', 20" Fir N.29°E. 2.0'
- ⑧ ^{25/30}/_{31/31} Set mon. at prorate position and marked new B.T.'s: 11" Fir S.87°W. 12.6, 5 1/2" Fir N. 7°W. 52.3', 9" Fir N.77°E. 23.9', 18" Fir S.68°E. 57.4'
- ⑨ ^{1/4}/₃₁ Set mon. at prorate position and marked new B.T.'s: 4 1/2" Fir S.13°E. 17.4', 6" Fir N.45°E. 188'
- ⑩ CE 1/6 Set mon. and marked B.T.'s: 14" Cedar N.74°E. 59.1', 13" Fir N.7°W. 21.1', 12" Fir S.64°W. 43.4'
- ⑪ E 1/6 ³⁰/₃₁ Set mon. and marked B.T.'s: 5" B.Oak N.64°E. 16.4', 5" B.Oak N.2°E. 25.9', 4" Fir N.83°W. 13.1'

SCALE 1"=500'
1" = .3048 meter

BASIS OF BEARINGS: North from solar observation taken near the southeast corner of Sec. 30

SURVEYOR'S CERTIFICATE

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE LAND SURVEYORS ACT IN NOV. 1981-MAY 19 82 AT THE REQUEST OF

U.S.D.A.
 Rodney D. Dawson
 RODNEY D. DAWSON LS 3621

COUNTY SURVEYOR'S CERTIFICATE

THIS MAP HAS BEEN EXAMINED THIS 13TH DAY OF July 1982 FOR CONFORMANCE WITH THE REQUIREMENTS OF THE LAND SURVEYOR'S ACT.

COUNTY SURVEYOR *Lawrence J. Brock*
 LAWRENCE J. BROCK RCE 13528
 DEPUTY

RECORDER'S CERTIFICATE

FILED THIS 14TH DAY OF July 1982 AT 10:40 A.M. IN BOOK 6 OF RECORD OF SURVEY AT PAGE 65 AT THE REQUEST OF the County engineer

FEE: \$ 5.00 FILE
 COUNTY RECORDER *Ila Diggs*
 DEPUTY *Frances Nicol*

RECORD OF SURVEY

for
 U.S.D.A- PLUMAS NATIONAL FOREST
 in
 Sec. 30 T.24N.R.10E. M.D.M., Plumas Co., Ca.

BURGESS LAND SURVEYS
 7036 "D" Hwy 99 S., Redding Co.

MAY 1982

SHEET 1 OF 1