



SURVEYOR'S CERTIFICATE

This map represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors Act at the request of Marjorie J. Reid in November 1983.



Clifford R. Brown
Clifford R. Brown RCE 22836

COUNTY SURVEYOR'S CERTIFICATE

This map has been examined for conformance with the requirements of the Land Surveyors Act this 29 day of February 1984. This Record of Survey does not constitute a subdivision under Division 2 of Title 7 of Government.

Lawrence J. Brock
Lawrence J. Brock

COUNTY RECORDER'S CERTIFICATE

Filed this 29th day of February 1984, at 2:55 p.m. in Book 6 of Record of Survey at page 111 at the request of the County Engineer.

Fee \$500
File No. 6780 by *Patricia Lacey* deputy
Ila Diggs, Plumas County Recorder

RECORD OF SURVEY

FOR
MARJORIE J. REID

tie to Sec Corner A portion of the Section 8 T24N R10E MDBM

Plumas County, California

Clifford R. Brown Engineering & Surveying
Rt. 1 Box 480B
Quincy, Calif.

ROAD CENTERLINE

Course	Dist.	Bearing
A	283.37	N 76°53'28"E
B	478.70	N 0°59'54"E
C	307.81	N 44°06'03"W
D	478.71	N 48°29'14"W
E	368.20	N 31°54'20"W
F	397.72	N 48°03'12"W
G	188.45	N 60°04'18"W
H	423.73	N 60°09'07"W
I	136.15	S 63°27'47"W
J	407.36	S 7°20'37"W
K	574.08	S 37°47'51"W
L	352.14	S 21°14'05"W
M	297.26	S 0°24'03"E
N	828.35	S 59°28'25"W

Comment
tie to 1/4 corner

6/5 Fd. BLM Brass Cap "1970"
7/8 Fd. B.T. 5" blk. oak N 31°E 7.9 (12 lks.)*
Fd. B.T. 10" blk. oak S 74°W 23.8' (36 lks.)*

5/8 1/4 cor. Set by single proportion
Fd. 25" oak stump no visible scribes 72.3' N 23°W
Glo rec. 25" oak N 2°W 87 lks. Not sufficient evidence to establish as orig. Bt.
set 3" alum cap tag RCE 22836
Bt 25" pine 298.1' N 4°W
Bt 12" pine 10.0' S 28°E

5/4 Fd. BLM Brass CAP "1971"
8/9 Fd. 12" oak 5.8' S 6°E *
Fd. 7" oak 23' N 29°W*

8/9 Fd. USFS Alum CAP "1983"
17/16 Fd. 12" pine with scribe N 89°E 99 lks.*
Fd. 18" pine B.T. S 36°E 47.2'
Fd. 6" fir B.T. S 52°W 9.3'

8/9 Fd. 1" square bar in mound of
17/16 rock per 3RS 70 w/tag RCE 13528
7" oak 4.0' N 53°E
22" rotted stump 38' S 85°E
(45" pine 62 lks S 73 1/4°)*

8/17 Fd 3" Brass CAP in concrete
RCE 11173 per 3RS 70
Accepted as 1/4 corner

7/8 1" I.P. tag RCE 292 in rock mound
18/17 per 4 RS 100 falls at angle in fence
8" blk. oak 17.3' S 63°W
12" pine 13.9' S 13°E
16" fir 29.3' N 38°E