

NOTES

The basis of bearings is the West line of Parcels 9 and 10, shown as S 0° 21' 30" E on 6 P.M. III, Plumas County Records.

This map shows a lot line adjustment filed in Book 441 O.R. page 525.

LEGEND

- — Found rebar and cap, L.S. 2843
- — Set rebar and cap, L.S. 2843

(R&M) — Record and measured information.

SCALE 1" = 50'

RECORD OF SURVEY  
FOR  
PORTOLA SHOPPING CENTER, et al  
PARCELS 9 and 10, 6 PM III  
Section 3, T22N R13E M.D.B.&M.  
PLUMAS COUNTY, CALIFORNIA  
SCALE 1"=50' JAN. 8, 1986

HAMBY SURVEYING INC.  
LICENSED LAND SURVEYORS

Portola, California  
P.O. Box 1209  
(916) 832-5571

SURVEYOR'S STATEMENT

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors Act at the request of Portola Shopping Center on Sept. 24, 1985.

*John W. Hamby*  
John W. Hamby  
LS 2843

COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Land Surveyors Act this 19th day of June, 1986.

*Lawrence J. Brock*  
by *R. Tom Stanton RCE 3055*  
Plumas County Surveyor  
Lawrence J. Brock R.C.E. 13528

RECORDER'S CERTIFICATE

Filed this 24th day of JUNE, 1986, at 10:58 A.M. in Book 7 of Record of Surveys at Page 76 at the request of the County Engineer.

Fee \$5.00  
File No. 7215

*ILA DIGGS*  
Plumas County Recorder

*Becky Cannock*  
Deputy