

NOTE

The distance of 746.65 on the center line of County Road 114, per (R-3), is to the point of intersection of the curve.



SCALE 1" = 200'

BASIS OF BEARING

The East line of the S.E. 1/4 of Section 30, shown as N 0° 22' 00" E on 6 R.S. 91 **is the basis of bearings shown on this map.**

LEGEND

○ = Set 1/2" capped rebar, LS 2843
● = Found point as noted
(R) = 6 R.S. 91
(R-1) = M.S. 5850
(R-2) = M.S. 3578

(R-3) = Plat of Easement, Lot 8, Section 30, Plumas Co. Rd. Dept.
(M) = Measured information
(c) = Computed information

SURVEYOR'S STATEMENT

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors Act at the request of Richard L. Jay, Trustee on Feb. 3 AND 6, 1984.

LICENSED LAND SURVEYOR JOHN W. HAMBY L.S. 2843 STATE OF CALIFORNIA

John W Hamby
John W. Hamby LS 2843

COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Land Surveyors Act this 25TH day of July, 1986.

Lawrence J. Brock
Plumas County Surveyor
Lawrence J. Brock RCE 13528

RECORDERS CERTIFICATE

Filed this 25TH day of July, 1986, at 1:00 P.m. in Book 7 of Maps at Page 81 at the request of the County Engineer.
Fee $5.00
File No. 621

Ila Diggs
Plumas County Recorder

by Patricia Nicol
Deputy

RECORD OF SURVEY
FOR

JOY TRUST

IN THE S.E. 1/4 OF SECTION 30, T. 22 N. R. 13 E., M.D.B.&M.
PLUMAS COUNTY, CALIFORNIA

HAMBY SURVEYING, INC.
Portola, California
P.O. Box 842
(916) 832-5571

Sheet 1 of 1

BRUNING 44-132 40893

84007

7 RS 81