


## Basis of Bearings

The Basis of Bearings of this map is the South line of the alley in Block 10, shown as N 61°02'29" E, in Book 8 of Record of Surveys at Page 66, Plumas County records.




## LEGEND

- FOUND Aluminum Cap LS 2843 per 8 RS 66
- FOUND Rebar with Plastic Cap LS 2843
- ▢ FOUND 1" I.P. tagged LS 3297 per 3 RS 137 unless noted otherwise
- FOUND tag in concrete LS 3297 per 3 RS 137
- SET 5/8" rebar with Aluminum Cap LS 2843
- SET Tag LS 2843 on top of concrete wall
- Computed Point per 8 RS 66
- (R1) RECORD per 8 RS 66
- (R2) RECORD per 665 O.R. 360
- (R3) RECORD per 3 RS 137
- (R4) RECORD per Bk. A Page 34 Map of Portola Townsite

95050

## SURVEYOR'S STATEMENT

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors' Act at the request of Jeff Mersky in September, 1995.



*John W. Hamby*  
John W. Hamby LS 2843

## COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Land Surveyors' Act this 5<sup>TH</sup> day of December, 1995.

*R. Tom Hunter*  
R. Tom Hunter RCE 30515  
PLUMAS COUNTY SURVEYOR  
License Expiration Date 3/31/96



## RECORDER'S STATEMENT

Filed this 5<sup>TH</sup> day of DECEMBER, 1995 at 8:20 a.m. in Book 10 of Record of Surveys, at page 90, at the request of the County Surveyor.

Fee 8.00  
File No. 7965

Judith Wells  
County Recorder  
by *Sue A. Peay*  
Deputy

RECORD OF SURVEY  
for  
Jeffrey & Judy Mersky

Lot 2 & Portion of Lot 1, Block 10  
& a portion of Lot 1, Block 7  
Portola Townsite, R.M. Bk. A, Pg. 34

A portion of Section 36  
T. 23 N., R. 13 E., M.D.M.

Portola ~ Plumas County ~ California  
Scale 1" = 40' September, 1995

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(916) 832-5571

SHEET 1 OF 1