

The Basis of Bearings of this map is the Westerly line of Lot 343 shown as S05°12'26"W, in Book 8 of Maps at page 123, Plumas County records.

NW Corner Section 22
Found BLM Brass Cap per 8 M 123 stamped as shown

T22N R13E
S16|S15
S21|S22
1986


Bearing Trees Blazed & Scribed with Bearing tree tags
15" Pine N21°45'W, 3.9'
10" Cedar N64°45'E, 27.7'
7" Pine S3°E, 34.6'
11" Pine S71°15'W, 38.3'

The Basis of Bearings of this map is the Easterly line of Lot 358 shown as S21°17'08"W, in Book 8 of Maps at page 123, Plumas County records.

N89°50'45"E
45.00'

Replaced Plastic Cap with Aluminum Cap

(R1)
Δ=82°27'11"
R=275.00'
L=395.75'



Lot P
Common Area

Revised Lot 358
15.76 acres

W 1/4 Corner Section 22
Found 5/8" rebar with Aluminum Cap stamped as shown

T22N R13E
1/4 S21 S22
1995
LS 2843

Bearing tree tags on
13" Juniper N15°23'W, 61.7'
8" Pine N62°42'E, 66.9'

Lot 358, Unit 15 "EAGLES NEST", 8 M 123

Note: all bearings, distances and curve data shown are record per Gold Mountain Unit 15 "EAGLES NEST", 8 M 123, except those shown with (R1 & R2) which are measured per Lot Line Adjustment 811 O.R. 386 and Document 2000-06144.

- LEGEND**
- FOUND point as described
 - FOUND Rebar with Aluminum Cap LS 2843
 - SET 5/8" Rebar with Aluminum Cap LS 2843
 - Nothing found or set
- (R1) Record per Document 2000-06144
(R2) Record per 809 O.R. 429
(R2) Record per 812 O.R. 719

RECORD OF SURVEY
for
Gold Mountain Ranch, Inc.

A portion of Section 22
T. 22 N., R. 13 E., M.D.M.
Plumas County ~ California
Scale 1" = 100' ~ November 2000

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571