



## LEGEND

- SET 5/8" Rebar & Aluminum Cap LS 2843
- FOUND Rebar with Plastic Cap LS 5055
- (R1) RECORD per 5 M 50 and measured.
- (R2) RECORD per L.L.A. and measured.



## SURVEYOR'S STATEMENT


This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors' Act at the request of Bill Valentine in Aug. 2001.



*John W. Hamby*  
John W. Hamby LS 2843

## COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Land Surveyors' Act this 20<sup>th</sup> day of November, 2001.



*R. Tom Hunter*  
R. Tom Hunter RCE 30515  
PLUMAS COUNTY SURVEYOR  
License Expiration Date 3/31/04

## RECORDER'S STATEMENT

Filed this 27<sup>th</sup> day of November, 2001 at 3:10 P.M. in Book 12 of Record of Surveys, at page 31, at the request of the County Surveyor.

Fee # 8.00  
File No. 2001-10251

Judith Wells  
County Recorder  
by *Karen Hancock*  
Deputy

## RECORD OF SURVEY for BILL VALENTINE

LOT 15, PLUMAS EUREKA ESTATES,  
UNIT NO. 7, (PHASE 1)

A portion of the NE 1/4 of Section 8  
T. 22 N., R. 12 E., M.D.M.  
Plumas County ~ California  
Scale 1" = 30', Sept., 2001

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571