


<p>T26N R8E R9E S25   S19 S30 1940</p> <p>CORNER No. 1</p> <p>FD. A GLO BCIP IN A MOUND OF STONE. (2) CORNER FALLS ON A GENTLE SOUTH SLOPE IN HEAVY TIMBER.</p> <p>FD. A 22" WHITE FIR, N10°E, 5.2' -HB REC. A 12" DOUGLAS FIR, N14 1/4°E, 5.3' (2) FD. A 22" YELLOW PINE, S44°E, 12.8' -HB REC. A 14" YELLOW PINE, S43°E, 13.2' (2)</p>	<p>T26N R8E R9E S25   S30 S36   S31 1940</p> <p>CORNER No. 8</p> <p>FD. A GLO BCIP IN A MOUND OF STONE. (2) CORNER FALLS ON A MODERATE SOUTHWEST SLOPE.</p> <p>FD. A 21" FIR SNAG, S77°W, 22.6' -HB REC. A 25" D. FIR, S77°53'W, 22.4' (3) FD. A 30" SUGAR PINE, N77°W, 24.4' -HB REC. A 30" SUGAR PINE, N76°11'W, 24.3' (3) FD. A 21" SUGAR PINE, S22°E, 30.0' -HB REC. A 20" SUGAR PINE, S21°21'E, 30.1' (3) FD. A 21" SUGAR PINE, N74°E, 51.2' -HB REC. A 23 1/2" SUGAR PINE, N74°19'E, 50.7' (3)</p>	<p style="text-align: center;"><b>CORNER NOTES</b></p> <p>HB = HEALED BLAZE VS = VISIBLE SCRIBING BCIP = BRASS CAPPED IRON PIPE (1) = REC. PER GLO 1869 (2) = REC. PER GLO 1940 (3) = REC. PER 7 RS 66 (4) = REC. PER 4 RS 145 (5) = REC. PER FOREST SERVICE CORNER RECORD T26N R9E SEC 30 FILE No. R-5</p>	
<p>CORNER No. 2</p> <p>T26N R9E 1/4 S19 S30 LS 3966 2001</p> <p>FD. A 3/4" IRON PIPE IN A MOUND OF STONE. NO RECORD - ACCEPTED AS 1/4 CORNER. SET A 3 1/4" ALUM. CAP ON A 5/8" ALUM. ROD AND FRESHENED MOUND. CORNER FALLS ON A STEEP WESTERLY SLOPE IN MEDIUM TO LARGE TIMBER, VERY LITTLE BRUSH.</p> <p>SCRIBED A 13" WHITE FIR, N6°W, 16.1' "T26N R9E 1/4 S19 BT" SCRIBED A 16" SUGAR PINE, S36°W, 22.0' "T26N R9E 1/4 S30 BT"</p>	<p>T26N R9E CORNER No. 9</p> <p>1/4 S30 S31 LS 3966 2001</p> <p>GLO RECORD STONE NOT FOUND. SET A 3 1/4" ALUM. CAP ON A 5/8" ALUM. ROD BY SINGLE PROPORTION. NO STONE AVAILABLE FOR MOUND. CORNER FALLS ON A MODERATE WEST SLOPE.</p> <p>SCRIBED A 7" DOUGLAS FIR, S30°E, 6.3' "T26N R9E 1/4 S31 BT" SCRIBED AN 11" DOUGLAS FIR, N9°E, 5.9' "T26N R9E 1/4 S30 BT"</p>		
<p>T26N R9E S19   S20 S30   S29 CAF 1966</p> <p>CORNER No. 3</p> <p>FD. A 2 1/2" ALUM. CAP ON A 3/4" IRON PIPE. CORNER FALLS ON A MODERATE SOUTH SLOPE IN HEAVY TIMBER.</p> <p>FD. A 32" WHITE FIR, S76°E, 27.9' -HB REC. A 30" WHITE FIR, S76°E, 27.1' (5) SCRIBED A 10" WHITE FIR, N33°E, 21.7' "T26N R9E S20 BT" SCRIBED A 19" YELLOW PINE, N51°W, 18.7' "T26N R9E S19 BT" SCRIBED AN 8" SUGAR PINE, S63°W, 14.8' "T26N R9E S30 BT"</p>	<p>T26N R9E CORNER No. 10</p> <p>E 1/16 S30 S31 LS 3966 2001</p> <p>SET A 3 1/4" ALUM. CAP ON A 5/8" ALUM. ROD IN A SMALL MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN TIMBER.</p> <p>SCRIBED A 17" WHITE FIR, N70°E, 9.3' "E 1/16 S30 BT" SCRIBED A 10" DOUGLAS FIR, S51°W, 22.4' "E 1/16 S31 BT"</p>		<p style="text-align: center;"><b>RECORD OF SURVEY</b></p> <p style="text-align: center;">FOR</p> <p style="text-align: center;"><b>USDA FOREST SERVICE</b> <b>PLUMAS NATIONAL FOREST</b></p> <p style="text-align: center;">"KINGSBURY RUSH 1"</p> <p style="text-align: center;">IN SECTION 30 OF T 26 N, R 9 E, MDM IN THE UNINCORPORATED AREA OF PLUMAS COUNTY, STATE OF CALIFORNIA</p> <div style="text-align: center; border: 1px solid black; padding: 5px;">  <p><b>DEL TERRA INC.</b> <b>SURVEYING</b> 1168 INDUSTRIAL ST. REDDING, CA 96002 PHONE (530) 241-8050</p> </div> <p style="text-align: center;">DATE: NOVEMBER, 2001 SHEET 2 OF 2</p>
<p>1/4 S25   S30 1940</p> <p>CORNER No. 4</p> <p>FD. A GLO BCIP (2). CORNER FALLS ON A STEEP NORTH SLOPE IN SNOW BRUSH AND PINES.</p> <p>FD. A 24" SUGAR PINE, S79°W, 35.8' -HB REC. A 16" SUGAR PINE, S80°W, 35.6' (2) FD. A 21" SUGAR PINE, N47°W, 88.6' -HB REC. A 14" FIR, N46°W, 89.8' (2)</p>	<p>CORNER No. 11</p> <p>LS 3621</p> <p>FD. A 1 1/2" ALUM. CAP STAMPED LS 3621 ON A #5 REBAR IN A MOUND OF STONE (4). CORNER FALLS ON A STEEP EAST SLOPE IN LARGE TIMBER.</p> <p>FD. A 20" DOUGLAS FIR, S8°E, 17.0' -HB REC. A 15" DOUGLAS FIR, S1°E, 17.2' (4) FD. A 17" DOUGLAS FIR, N30°E, 27.5' -HB REC. A 10" DOUGLAS FIR, N30°E, 27.8' (4)</p>		
<p>CORNER No. 5</p> <p>LS 3621</p> <p>FD. A 1 1/2" ALUM. CAP STAMPED LS 3621 ON A #5 REBAR IN A MOUND OF STONE (4). CORNER FALLS ON A STEEP SOUTHEAST SLOPE IN MEDIUM TO LARGE TIMBER.</p> <p>FD. AN 18" INCENSE CEDAR, N12°E, 17.7' -HB REC. A 17" CEDAR, N11°E, 17.1' (4) FD. A 32" YELLOW PINE, S47°W, 9.4' -HB REC. A 30" YELLOW PINE, S50°W, 9.0' (4)</p>			
<p>T26N R8E R9E S1/16 S25   S30 LS 5287 1985</p> <p>CORNER No. 6</p> <p>FD. A 3" ALUM. CAP ON A 2 1/2" ALUM. PIPE IN A MOUND OF STONE (3). CORNER FALLS ON A MODERATE SOUTHWEST SLOPE.</p> <p>FD. AN 8" SUGAR PINE, N49°E, 7.0' -HB REC. A 7" SUGAR PINE, N51°30'E, 6.9' (3) FD. A 9" SUGAR PINE, N12°W, 16.4' -HB REC. A 9" SUGAR PINE, N10°45'W, 16.0' (3)</p>			
<p>SE 1/16 S30 LS 3966 2001</p> <p>CORNER No. 7</p> <p>SET A 3 1/4" ALUM. CAP ON A 5/8" ALUM. ROD IN A SMALL MOUND OF STONE. CORNER FALLS ON AN EAST SLOPE IN BRUSH AND TIMBER.</p> <p>SCRIBED A 6" WHITE FIR, S73°W, 9.4' "SE 1/16 S30 BT" SCRIBED A 5" WHITE FIR N19 1/2°W, 22.4' "X BT"</p>			