


## SURVEYOR'S STATEMENT


This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Professional Land Surveyors' Act at the request of Ricky Ross in November, 2004.



*John W. Hamby*  
John W. Hamby LS 2843  
License Exp. 6-30-06

## COUNTY SURVEYOR'S STATEMENT


This map has been examined in accordance with Section 8766 of the Professional Land Surveyors' Act this 25<sup>th</sup> day of January, 2005.



*R. Tom Hunter*  
R. Tom Hunter RCE 30515  
PLUMAS COUNTY SURVEYOR  
License Expiration Date 3/31/06

## BASIS OF BEARINGS

The Basis of Bearings for this map is the Southerly line of Parcel 1, shown as S81°59'30"W on the map filed in the Office of the Recorder of Plumas County in Book 11 Record of Surveys, at page 44.



## LEGEND

- FOUND Rebar with Aluminum Cap LS 2843 per 11 RS 44
- FOUND Rebar with Plastic Cap stamped RCE 22836 per 7 RS 96
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Nothing found or set
- (R1) RECORD per 11 RS 44
- (R2) RECORD per 745 OR 130
- (R3) RECORD per 6 M 15

## RECORDER'S STATEMENT

Filed this 25<sup>th</sup> day of January, 2005 at 3:13 p.m. in  
Book 13 of Record of Surveys, at page 85, at the request  
of the County Surveyor.

Kathleen Williams  
County Recorder  
Fee: 8.00  
By: Sue A. Peay  
Document No. 2005-926  
Deputy

RECORD OF SURVEY  
for  
RICKY ROSS

Parcel 1 of 11 RS 44  
Being a Portion of Lot 1, per 6 M 15  
A portion of the NE 1/4 of Section 3  
T. 22 N., R. 13 E., M.D.M.

Unincorporated Plumas County ~ California  
Scale 1" = 50' November, 2004

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571