



BASIS OF BEARINGS

Found 3/4" Rebar
(R1) No Cap, set
tag LS 2843

The Basis of Bearings for this map is the East Line of Lot 11,12
and 13 shown as S00°27'00"E on the map filed in the office of the
Recorder of Plumas County in Book 4 of Maps at page 5.

**SURVEYOR'S STATEMENT**

This map correctly represents a survey made by me or under my direction
in conformance with the requirements of the Professional Land Surveyors'
Act at the request of Mary Elizabeth Farrell in August, 2005.



John W. Hamby
John W. Hamby LS 2843
License Exp. 6-30-06

Found 3/4" Iron Pipe
with Tag, LS 3297,
S87°39'25"W 0.70' from
computed corner. No
Record.

Found 3/4" Rebar
(R1) No Cap, set
tag LS 2843

S00°27'00"E
101.54' (R1&M)

Found 3/4" Iron Pipe
with Tag, LS 3297,
S87°39'25"W 0.70' from
computed corner. No
Record.

Found 3/4" Rebar
(R1) No Cap, set
tag LS 2843

S00°27'00"E
101.54' (R1&M)


Found 3/4" Iron Pipe
with Tag, LS 3297,
S87°39'25"W 0.70' from
computed corner. No
Record.

Found 3/4" Rebar
(R1) No Cap, set
tag LS 2843

S00°27'00"E
101.54' (R1&M)

COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the
Professional Land Surveyors' Act this 5th day of
October, 2005.




R. Tom Hunter
R. Tom Hunter RCE 30515
PLUMAS COUNTY SURVEYOR
License Expiration Date 3/31/06

RECORDER'S STATEMENT

Filed this 5th day of October, 2005 at 10:55 a.m. in
Book 13 of Record of Surveys, at page 134, at the request
of the County Surveyor.

Fee: 8.00
Document No. 2005-10774

Kathleen Williams
County Recorder
By: *Melinda Rothen*
Deputy



RECORD OF SURVEY
for
Mary Elizabeth Farrell

Lot 12 Dixie Valley Properties, Unit 1, 4 Maps 5
within Section 6, T. 24 N., R. 15 E., M.D.M.

Plumas County ~ California
Scale 1" = 60' August, 2005

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571